

Belden Deutschland GmbH • Im Gewerbepark 2 • 58579 Schalksmühle

August 3, 2017

Dear Valued Customer,

This letter serves as your formal notification that Belden is discontinuing **specific modules inside the Lumberg Automation ASi-Interface (ASL) product line, effective immediately.**

The specific 0910 ASL xxx Modules contain components which have become obsolete. Belden has a limited stock of these devices that will last until final delivery date (December 29, 2017).

For each discontinued product an alternative replacement product is available, please refer to the list below.

Discontinued Product(s)

Discontinued Product	Description	Suggested Alternative	Description
0910 ASL 134	ASi V2.1, 2DI 2DO M12 connection	0910 ASL 135	ASi V2.1, 4DI 4DO M12 bus connection
0910 ASL 404	ASi V2.1, 2DI 2DO Flat cable bus connection	0910 ASL 408	ASi V2.1, 4DI 4DO Flat cable bus connection infrared interface for the addressing
0910 ASL 409 L	ASi V2.11, 4DI Flat cable bus connection infrared interface for the	0910 ASL 409	ASi V2.1, 4DI Flat cable bus connection infrared interface for the addressing
0910 ASL 410	ASi V2.1, 2DI 2DO Flat cable bus connection	0910 ASL 408	ASi V2.1, 4DI 4DO Flat cable bus connection infrared interface for the addressing
0910 ASL 419	ASi V2.1, 8DO Flat cable bus connection infrared interface for the addressing	0910 ASL 403	ASi V2.1, 4DO Flat cable bus connection
		0910 ASL 408	ASi V2.1, 4DI 4DO Flat cable bus connection infrared interface for the addressing
0910 ASL 428	ASi V2.11, 4DI 4DO Flat cable bus connection infrared interface for the addressing	0910 ASL 408	ASi V2.1, 4DI 4DO Flat cable bus connection infrared interface for the addressing
		0910 ASL 405	ASi V3.0, 4DI 4DO Flat cable bus connection
0910 ASL 429	ASi V3.0, 4DI Flat cable bus connection infrared interface for the addressing	0910 ASL 402	ASi V3.0, 4DI Flat cable bus connection

The standard warranty terms will be honored for all units shipped to date. For more information on Belden's Long Term Product Support Policy for Industrial Connectivity products, please visit www.belden.com/ltps. Special contracts in place and active prior to the announcement date will be honored according to the terms of that contract, with regard to product availability, warranty, or support terms.

Discontinuation Milestones – 0910 ASL xxx

Milestone	Date
Discontinuation Announcement Date	August 3, 2017
Last Order Date	October 31, 2017
Last Shipment Date	December 29, 2017

A detailed list of all discontinued part numbers can be found at the end of this letter.

If you have any questions or for assistance selecting alternative products, please contact your local Belden sales representative ([North America contact information](#) and [International contact information](#)).

Sincerely,
Belden Deutschland GmbH



i.V. Joachim Kiera
Belden Deutschland GmbH
Manager Product Management



i.A. Paul Just
Belden Deutschland GmbH
Product Manager I/O Systems

Discontinued Part Numbers – 0910 ASL xxx

Last Order Date: October 31, 2017

Discontinued Part Number	Description	Replacement	
74902	0910 ASL 134	74903	0910 ASL 135
10920	0910 ASL 404	26819	0910 ASL 408
		10921	0910 ASL 405
63354	0910 ASL 409 L	26823	0910 ASL 409
26821 US Order ID: 900000969	0910 ASL 410	26819	0910 ASL 408
46877	0910 ASL 419	10919 US Order ID: 900000192	0910 ASL 403
		26819	0910 ASL 408
87944	0910 ASL 428	26819	0910 ASL 408
		10921	0910 ASL 405
88276	0910 ASL 429	10918	0910 ASL 402

Belden, Belden Sending All The Right Signals, Hirschmann, GarrettCom, Tofino Security, Lumberg Automation and the Belden logo are trademarks or registered trademarks of Belden Inc. or its affiliated companies in the United States and other jurisdictions. Belden and other parties may also have trademark rights in other terms used herein.